




Nº 126 SERVICE BULLETIN



Joe Blackwell
Director, Parts Sales &
Technical Support

Susan White
Parts Sales
Manager

Patty Schraps
Parts Stockroom
Manager

Chas Siddiqi
Technical Support
Engineer

Jay Alfer
Technical Support Doc.
Administrator

TO: Parts & Service Managers

DATE: September 19, 2001


SUBJ: The Bubble Level is back!

Symptom:

Game play is either too fast or too slow. Pinballs tend to drain quickly or average ball time is high. Game performance is low.

Problem:

Game is not set up properly with the desired 6.5° pitch.



Solution:

With the bubble level now provided in our games (first included with our current game **MONOPOLY®**), adjustment to the Leg Leveler(s) can now be made accurately.

Procedure:

Start adjustment with the leg levelers *turned all the way in*. **View** the bubble in the level provided on the right side wood rail (see above). **Adjust** the front or rear levelers as necessary to cause the bubble to float between the two (2) black lines. **Note:** For side-to-side leveling, use a pinball to roll down the center of the playfield.

YOUR PLAYFIELD PITCH IS NOW AT 6.5° AS REQUIRED FOR PROPER GAME PLAY!

For custom adjustment greater than >6.5° can be achieved by turning out the rear leg leveler(s), however, **it is not recommended**.

Please *phone* or *eMail* with any questions or comments at the below numbers or address.

• 2020 Janice Ave • Melrose Park, IL 60160 • Tel 708-345-7700 (Option 1) • Toll-Free (USA/Canada) 1-800-542-5377 • Fax 708-345-7889 •